

ClubSwan 42 Headsail & Spinnaker Halyards

Notice #06/2019

A question has been asked if it is possible to remove or hoist to the top of the mast the 2nd Headsail Halyard and/or the 2nd Spinnaker Halyard.

This questioned has been asked previously and answered in Swan 42 Class Technical Questions and Answers.

To clarify.

- Removal of the 2nd Headsail (Jib) Halyard is not permitted.
- Removal of the 2nd Spinnaker Halyard is not permitted.
- Hoisting (skying) the 2nd halyards with a retrieval line is not permitted.

Andrew Yates ClubSwan 42 Class Measurer 08 October 2019