


CLUBSWAN 36

Notice #03/2023

Masthead Upper Limit Mark

Teams that are missing the Upper Limit Mark are requested to add it in the location shown below.

Distance in mm to centre of main halyard pin.



Andrew Yates
ClubSwan 36 Class Measurer
10 May 2023