



Notice #03/2024


### **Limitation of Foil Extension**

The ClubSwan 36 Class Rules for 2024 permit moving the foil stops to allow the foil to be extended further the position of the revised stop position is detailed in ClubSwan 36 Class Notice #02/2024.

This increase the load on the foil has the potential to be beyond the foil design loads and it is the responsibility of the CS36 Owner and sailing teams to manage the load or the foil has the potential to break.

**At boat speeds greater that 18 knots to prevent breakage the CS36 foil must be retracted by at least 320mm from the maximum extension.**

Teams will be aware that moving the foil at higher boat speeds is not possible and the boat should be slowed down to allow the foil to be moved.



No claim can be made against Nautor Swan Srl, ClubSwan Racing Srl or JK YD for any direct or indirect damage or breakage caused by a failure to retract the foil at 18 knots of boat speed or any direct or indirect damage or breakage caused by attempting to move the foil without slowing the boat.